

Release Notes RockWorks 1.41

RockNet 300 Firmware

The following bugs have been fixed in version 1.41:

1. Possible audio artifacts if a unit is set to external sync
2. Possible audio artifacts during a preset load
3. MY card can block system communication when in MY8 legacy mode
4. Loading snapshots do not update gain and phantom settings correctly
5. Loading presets overrides CH80 mode setting and sets the system back to CH160 mode
6. Possible buffer overrun (E00010) during fast & frequent link changes
7. Possible incorrect gain settings after fast & frequent link changes
8. Invoking the special menu is sometimes not possible when the system shows connection state errors
9. Possible audio artifacts on units in external sync mode with unconnected link input port
10. Desk/Slot-Id collision is not correctly resolved after a preset change
11. Head amp remote disfunctional when the HA cable is already connected and the card is set back to Slot-ID 1 from a different Slot-ID
12. No audio @ -14 dB HA gain setting on channel 2-8 (RN.301.MI) or channels 2-16 (RN.101.IO)

RockWorks and RockFlash

The following bugs have been fixed in version 1.41:

1. Usually, the "live" preset of a RN.341.MY is shown in bold yellow font. However, after editing a preset this font has been used for the selected preset instead
2. The update-file is now copied into the documents folder (MAC)
3. The MAC version installer now creates the RockWorks and RockFlash applications in a sub-folder in the program directory
4. Connecting via ethernet is now possible with the MAC-version
5. Rarely, loading a snapshot did not update the device-view correctly
6. Rarely, loading a snapshot did not update the HA gains correctly
7. After a system reset the system sometimes changed to CH80 mode
8. The "Import Preset" function was inconsistent
9. Device and channel names were displayed incorrectly or even not at all ("Power-PC" MAC-version only)